
Village of South Dayton - Tank Replacement



The Village's existing 250,000 gallon painted steel water storage tank, (shown right) was slowly leaking and the protective coating was failing. This firm designed a solution for a new tank and prepared bidding documents. The small size of the site and the poor soil conditions presented unique challenges of this project. There was a lot of coordination between the owner, the regulatory agency, and the contractor leading up to and during the construction phase of this project. A glass-fused-to-steel bolted storage tank (shown above) was chosen for this project.



